## **SBD CM REVIEW FORM**

To: Business Opportunity Support Services Division - Construction

From: SBD CM - Ileana Quintana

Department: Water & Sewer Department

Contact: Jose Vilabov

Date: 10 / 24 / 2012

**PROJECT NUMBER: RPQ P0086** 

PROJECT TITLE: Mechanical Integrity Testing Repair IW-13 thru IW-17 SDWWTP IW-1N thru IW-4N NDWWTP

PROJECT LOCATION: SDWWTP 8950 SW 232 Street / NDWWTP 2575 NE 151 Street

SCOPE OF WORK/DESCRIPTION: Consists of furnishing all labor, materials and equipment to perform mechanical integrity testing of 21 existing Floridan Aquifer injection wells including cleaning, video surveying and gamma logging; remove 9 existing 24" gate valves; furnish and install 9 new butterfly valves, sand the outside of the piping inside the 5 foot-deep concrete pits; coat the outside of piping with an epoxy such as Bitumastic 300M and encase it in PVC pipe sleeve, fill the annular space with grout to prevent further corrosion of the portion of the pipe inside the pits and all associated and appurtenant items.

## SPECIAL REQUIREMENTS:

TRADES	AMOUNT	COMMENTS
		Wang Wall Contrator License
All materials and labor to complete the testing and repairs to the monitoring wells	\$1,975,500.00	Primary scope of work; no ancillary work to be subcontracted.
·		
	\$1,975,500.00	
Dedicated allowance	\$59,265.00	
Contingency Allowance	\$197,550.00	
Total Construction Cost Estimate	\$2,232,315.00	
	•	
	1/1	$\frac{1}{2}$
	///	/ / ///

Small Business Development Signature:

Date: 10 / 25 / 2012

\* Trades/Subtrades identified for possible subcontracting opportunities identified by SBD CM